

US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	12/12/2012	1650		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
Containment Branch Recovery Team 3 (CBR-3)	Name:	Dan Capone START/US EPA	From:	12/12/2012 0700
	Position:	Operations Section Chief	To:	12/12/2012 1600
7. Personnel Roster Assigned				
<u>Name</u>	ICS Position			
Dan Capone	Operations Section Chief			
Rex Johnson	Containment Branch Director			
Sean Kane	Field Team Lead/CBR-3			
8. Activity Log				
Activity Area	(MP 33.00A-RDB & MP 33.25)	LAT		LAT
		Various		Various
		(DD.MMMM)		(DD.MMMM)
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA			
	DENSITY OF OIL /SHEEN			
Total Collection Points				
Total Boom Deployed				
Activity	<u>Weston/START CBR 3 Team Activity:</u> General oversight documentation (photo and written) of Enbridge bathymetric survey team # 1 led by Luke Hodges (Stantec). Enbridge field team completed survey activities within the MP 33.00A (RDB) operational area. Completed transects include: MP 33.00A-D (49 survey points), MP33.00A-N (10 survey points). Bathymetric survey measurements were also conducted directly upstream of the sediment 'pine tree' traps (11 survey points), and directly on the sediment trap (12 survey points). Enbridge field team conducted transect stake set-up within the Morrow Lake Delta (Delta A) for operations to be conducted on 12-13-2012.			
Health and Safety Issues	None			
Comments	Water flow velocity and surface water elevation measurements were obtained for every transect line.			

	Cylindrical Sampling Device (CSD) #5 was removed prior to intrusive survey activities within the MP 33.00 RDB.
--	--

	Detailed field notes will be found in CBR-3 logbook.
--	--